## Certificate

## Inspection of the welding quality requirements according ISO 3834

Certificate no.: 01 202 E/A-09 5343/01

Name and address of the manufacturer:

Specifications:

Manufacturing Plant:

Scope:

MACOGA, S.A. C/ Leira, s/n E - 15680 ORDENES (LA CORUÑA) SPAIN

It is hereby certified that the manufacturer has furnished proof of the comprehensive quality requirements according to the test basis. The mentioned company

- operates a quality system which ensures that the manufacture and inspection of the products stated in our report, are in compliance with applicable technical standards and regulations;
- employs qualified supervisory and inspection personnel;
- has qualified welding processes and welding personnel;
- has adequate facilities permitting manufacture and inspection of welded products.

EN ISO 3834-2

The scope of the inspection and other relevant data are given in the annex to the certificate.

MACOGA, S.A. C/ Leira, s/n

E - 15680 ORDENES (LA CORUÑA)

**SPAIN** 

Test Report no.: 92500906

Valid until: November 30, 2021

Cologne, February 14, 2019 i.A. Eng. Achim Makowka

TÜV Rheinland Industrie Service GmbH Certification Body for welding manufacturers Am Grauen Stein, D-51105 Köln Certification Body for Manufacturer Qualification

M-012-E-Zert-3834-2-Rev-24





