

Certificate

Inspection of a manufacturer and welding shop

acc.AD 2000-Merkblatt HP 0 and DIN EN ISO 3834-2

Certificate no.:

01 202 E/A-15 5343/Rev.00

Name and address of the
manufacturer:

MACOGA, S.A.
C/ Leira, s/n
E-15680 ORDERES (LA CORUÑA)
SPAIN

It is hereby certified that the manufacturer has furnished proof of the quality requirements. The above-mentioned company

- has facilities permitting manufacturing and inspection in conformity with the present technical standard,
- operates a quality system which guarantees that manufacturing and inspection of the products stated in our report are in conformity with the technical codes and regulations,
- employs qualified supervisory and inspection personnel.

Inspection:

according to AD 2000-Merkblatt HP 0 and DIN EN ISO 3834-2

Test Report no.:

33394666

Area of Application:

The scope of the inspection and all other relevant data are given in the annex to the certificate.

Production Location:

MACOGA, S.A.
C/ Leira, s/n
E-15680 ORDERES (LA CORUÑA)
SPAIN

Valid until:

November 30, 2018

Cologne, December 14, 2015


i.A. Dipl.-Ing. S. Kreß



TÜV Rheinland-Certification Body for
Pressure Equipment
TÜV Rheinland Industrie Service GmbH
Am Grauen Stein, D-51105 Köln

M-010-Rev3

www.tuv.com

 **TÜVRheinland®**
Precisely Right.

Certificado

Inspección de fabricante y taller de soldadura

AD 2000-Merkblatt HP0

Certificado N°.:

01 202 E/A-15 5343/Rev.00

Nombre y dirección del fabricante

MACOGA, S.A.
C/ Leira, s/n
E-15680 ORDERES (LA CORUÑA)
ESPAÑA

Este certificado esta emitido para certificar que el fabricante cumple con los requerimientos de calidad de la mencionada compañía

-Posee las facilidades que permiten una fabricación e inspección en conformidad con el presente norma

-Posee un sistema de calidad el cual garantiza la fabricación, e inspección de los productos que se relatan en nuestro informe en conformidad con las regulaciones y códigos técnicos,

-Posee personal debidamente cualificado

Inspección:

AD 2000-Merkblatt HP0 y DIN EN ISO 3834-2

Informe N° .:

33394666

Area de aplicación :

El ambito de la inspeccion y otros datos relevantes se citan en el informe de inspección

Planta de Produccion :

MACOGA, S.A.
C/ Leira, s/n
E-15680 ORDERES (LA CORUÑA)
ESPAÑA

Valido hasta

30 de Noviembre 2018

Colonia, 14 de diciembre 2015


i.A. Dipl.-Ing. S. Kreß



TÜV Rheinland-Certification Body for
Pressure Equipment
TÜV Rheinland Industrie Service GmbH
Am Grauen Stein, D-51105 Köln

M-010-Rev3

www.tuv.com

 **TÜVRheinland®**
Precisely Right.